

Bronx-Whitestone Bridge Biennial Inspection



Client: HNTB Corporation

Owner: Triborough Bridge & Tunnel Authority

Project Location: New York, NY

GPI provided one team, including Team Leader and Assistant Team Leader for the Biennial Inspection of the Bronx-Whitestone Bridge. All work was done in accordance with the NYSDOT Bridge Inspection Manual and the FHWA Inspection Procedures for Fracture Critical Members. GPI's Team Leader also served as principal liaison between the TBTA Facility Engineer and the other inspection teams. Work included hands-on inspection of all bridge members, reporting in accordance with the NYSDOT bridge inventory procedures, and flag preparation, as necessary.