

Department of Environmental Protection Buckman Lock



Structure Restoration - Structure Improvements

Client/Owner: Department of Environmental Protection

Project Location: Palatka, FL

UESI installed DEP supplied bulkheads and dewatered the lock. Monitoring of the structure for movement and monitoring of the surrounding ground water. Removal of fauna to DEP specifications. Debris and sediment removal from the lock floor. Installed new manatee grates in the lock chamber. Installation of an HDPE fender system. Removal, maintenance, and replacement of mooring bits and removal of existing check posts.